

HydraXPPC Update 1.32 --> 1.35

Version: 1.32 to 1.35

Date: 6.7.2009

IMPORTANT!

Model / software version	Software version of remote control in PDA
Only for Plus / version 1.26	HydraPlusPPC101 or HydraPlusPPC110
All the models / From version 2.12	HydraXPPC120
All the models / From version 2.40	HydraXPPC130
All the models/ From version 2.50	HydraXPPC132
All models/From version 3.00	HydraXPPC135

SOFTWARE INSTALLATION FROM STORAGE CARD OR FORM THE DEVICE

HydraXPPC folder (supplied by the provider or from Internet) has the next files:

1. _ReadmeSD.txt
2. HydraPlusPPC.dat (Key. If you don't have this file, must be requesting it to your provider) it's important to have a security copy of this file.
3. SoftXXX.CAB (Installer of the remote control software, HydraXPPC, where xxx is the version number)
4. ManualxxxEs.CAB (Installer of the manual for the PDA, where xxx is the version number)
5. PocketXPDFxxx.CAB (Freeware software that allows to you read pdf files into the PDA, files as the previous manual)

This software, usually, is in your Storage Card. If you have updated it from Internet, it must be copied to your Storage Card or device, using your ActiveSync application.

We recommend using the Storage Card, useful besides as Backup.

INSTALLATION PROCCES

1. Access to the HydraXPPC folder, usually in your Storage Card, using the File Explorer.
2. Open HydraXPPC folder.
3. Execute SoftXXX.CAB and follow the instructions. We recommend installing the program in the Device.
4. Copy HydraPlusPPC.dat file (key) in folder: My Device/LT
5. If you want the manual in the PDA, execute ManualXXXEs.CAB
6. Optionally, if your PDA hasn't other software to read pdf files, execute PocketXPDFxxx.CAB

Direct accesses will be created in the Start menu, if possible, for all these applications. The Start menu is configured in Start/Settings/Menus.

IMPROVEMENTS

Program start process

HydraXPPC software searches the “key” by alls Flash cards connected to the PDA.

Communication process

Improvements in communication process due to a driver change. From this version **Packet** driver is used; and **IPX** driver is used no more.